




Flood Inspection Records

Note (3 October 2017): BOPRC staff names withheld under the Local Government Official Information and Meetings Act 1987 on the basis of protecting the privacy of natural persons (section 7(2)(a) of the Act) and/or for maintaining the effective conduct of public affairs through protecting officers, employees, and persons of Council from improper pressure or harassment (section 7(2)(f)(ii) of the Act).

Night shift – 7pm Wednesday 5th April 2017 to 7am Thursday 6th April 2017

Time (24hr)	Observations	Actions
01:33	College Road Floodwall <ul style="list-style-type: none">No obvious signs of seepage	No action required – continued to next site
01:43	Laws Bend Stopbank <ul style="list-style-type: none">River level is approximately 2m below SB crestNo obvious signs of seepageWater on the road at the bend – appears to be surface flooding as there is no sign of water movement at all	No action required – continued to next site
01:55	Thornton Boat Ramp <ul style="list-style-type: none">River level is up to road levelGeneral surface flooding water around toilets coming across road to meet the river level 	No action required – continued to next site
≈2:05	Grieg Road Flood wall <ul style="list-style-type: none">River Level is approximately 1.2m below top of floodwallNo obvious signs of seepage	No action required
≈5:27	College Road Floodwall <ul style="list-style-type: none">No obvious signs of seepage	No action – continued on to Hydro Road inspections